

APPENDIX E

Deteriorated Buildings



Exhibit E-1: A deteriorated building (Tax map number 0600-128-6-86.3) located on the east side of Peconic Avenue, north of the parking lot access road.



Exhibit E-2: Side view of Exhibit E-1 (Tax map number 0600-128-6-86.3) located on the east side of Peconic Avenue, north of the parking lot access road.



Exhibit E-3: Side view of a deteriorated building (Tax map number 0600-128-6-73.1) located on the south side of East Main Street, east of the major access road into the parking lot.



Exhibit E-4: Rear view of a deteriorated building (Tax map number 0600-128-6-75) located on the south side of East Main Street, north of the parking lot within the southwest portion of the EMSURA.



Exhibit E-5: Rear view of a deteriorated building (Tax map number 0600-128-6-77) located on the south side of East Main Street, north of the parking lot within the southwest portion of the EMSURA.



Exhibit E-6: Side view of a deteriorated building (Tax map number 0600-129-1-10) located east of the parking lot access road within the southeast portion of the EMSURA.



Exhibit E-7: Side and rear view of Exhibit E-6 (Tax map number 0600-129-1-10) located east of the parking lot access road within the southeast portion of the EMSURA.



Exhibit E-8: Rear view of deteriorated buildings (Tax map number 0600-129-1-12 and part of 129-1-11) located on the south side of East Main Street, west of McDermott Avenue and north of the parking lot within the southeast portion of the EMSURA.



Exhibit E-9: Side view of a deteriorated building (Tax map number 0600-129-1-17) on the south side of East Main Street, just east of the East End Arts Council.



Exhibit E-10: Side view of a deteriorated building (Tax map number 0600-129-1-21) located on the south side of East Main Street, just west of McDermott Avenue.



Exhibit E-11: Side view of a deteriorated building (Tax map number 0600-129-4-13.1) located west of McDermott Avenue behind structures fronting on East Main Street.



Exhibit E-12: Side view of a deteriorated building (Tax map number 0600-129-4-13.2) located west of the access road/parking lot on the south side of East Main Street, west of McDermott Avenue.



Exhibit E-13: Side view of a deteriorated building (Tax map number 0600-129-4-10.6) located behind the Thrift Store on the south side of East Main Street within the southeast portion of the EMSURA.



Exhibit E-14: A deteriorated building (Tax map number 0600-129-3-13) located on the north side of East Main Street, just west of Ostrander Avenue.



Exhibit E-15: A deteriorated building (Tax map number 0600-129-3-12) located on the north side of East Main Street, just west of Exhibit E-14.



Exhibit E-16: A deteriorated building (Tax map number 0600-129-1-8.2) located on the north side of East Main Street, west of East Avenue.



Exhibit E-17: A view of the eastern portion of Exhibit E-17(Tax map number 0600-129-1-8.2) located on the north side of East Main Street, west of East Avenue.